DAILY WORK ORDER	
Bossert Manufacturing	Work Period: 8/28/87
Contractor: O. H. Materials Contractor Rep.: Keith Risner	
WORK PLANNED/AUTHORIZED: 1.) Finish cleaning sump #3 and decon sump equipment. 2.) Lasering in area #12 along w/sumps #43, #44, #34 and #35. 3.) Decon Bobcat w/magnet and take wipe sample. 4.) Check on the disposal of NPCB and PCB oil. 5.) Clear out lower holding bins on Decon and inventory. 6.) Check on a Backhoe (Case 580D). 7.) Setup supply truck for NJ run.	Yes No Continues 1.) () () (x) 2.) () () (x) 3.) (x) () () 4.) () (x) 5.) (x) () ()
(3) Vans (1) Fick-up Truck (1) Decon trailer (3) Bobcats (1) Command Post Trailer (1) Crew Trailer (3) 12K Pools (1) Portable Eye Wash (2) Car (6) Radioes (1) 50K Pool (1) Water Treatment System w/ appurtenances (2) High-Pressure Water Laser w/hoses (1) Mini-Trackhoe (20) Propane tanks (1) Cascade System (1) 6-CY Dumpster (1) 3-in	All Authorized COMMENTS: (4) Porta-Johns
PERSONNEL AUTHORIZED: (1) Foreman (3) (1) Laborer (1) Lab Technician (2) (7) Clean-up Technician (1)	(2) Foreman (2) (1) Field Clerk (5) Clean-up Technician (2)
Contractor Signature: Kuth D. Risner Date:	QSC Signature: Lack D. Hum. Date:
4-28-87	8 - 28 - 87